During the following weeks that have past, the vehicle is almost done, and we had Mr. Meyer test drive it. The vehicle drives great. The chassis was sanded off and painted black. Most of the parts for the car were painted black to match the body color. The wiring for the chassis is done as well. Seat belts and the car seat are installed. Now we are in the process of reassembling the vehicle. Fire walls are still to be installed. Ken from FiberGlassSolution came in to help buff fiber glass body.



